

ECR #: P4

Tracker #: 7

Status: Ratified

Title: Change Modem_Spkr Description from Output to Input

Release Date: June 2, 1997

Impact: Clarification

Spec Version: NLX 1.2

Summary:

In Table B1, the description of the MODEM_SPKR signal on pin Y13 incorrectly calls out the signal as an output; this signal is input, and the table needs to be corrected. In the table, only this signal description is changed, and only the underlined portion is changed.

Background:

Clarify the I/O designation and description of the MODEM_SPKR signal on pin Y13 to show that it is an input.

Change Current Specification As Shown:

In Table B1, correct the description of the signal on pin Y13 as follows:

Pin	Signal Name	Type	I/O *	Description	Signal Type
Y13	MODEM_SPKR	AUDIO	I	Analog mono <input input="" motherboard<="" signal="" to=""/> from telephony device.	Analog 1V RMS